

## City of Mansfield Stormwater Infrastructure

- Box Culvert
- Inlet, Poor Condition

Inlet

Stormwater Outlet