



City of Mountain View Stormwater Infrastructure

- Box Culvert
- Inlet, Poor Condition
- Inlet
- ▲ Stormwater Outlet

